
City of Baltimore Wet Smoke and Dyed	Page 1 of 2	
Sewershed: Gwynns Falls	Company: Savin	Date: 7/9/2009
Test to be performed:  Smoke Dyed Water X	Ground Condition:  Dry ✓ Damp ☐ Wet ☐	Supervisor: <u>JAW</u>
Manhole_ID: S03CC1017MH	Test ID: <u>D1032-026011</u>	Notification Made: NA (Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Start of Survey	
0			Water Level	
0			Start of Survey	
0			Manhole	S05YY_003MH
0			Water Level	
134	10		Tap Factory	From 3909 Vesta
134			Dye Test Visible	@ TF - toilet
134			Dye Test Visible	@ TF - downspout
134			Manhole	S05YY_029MH
134			End of Survey	DYE TEST COMPLETED
216.4646454			Manhole	S01CC1002DE

City of Baltimore W Smoke and Dy	Page 2 of 2	
Sewershed: Gwynns Falls	Company: Savin	Date: 7/9/2009
Test to be performed:  Smoke Dyed Water X	Ground Condition:  Dry ✓ Damp ☐ Wet ☐	Supervisor: <u>JAW</u>
Manhole_ID: S03CC1017MH	Test ID: <u>D1032-026011</u>	Notification Made: NA (Residents, Fire, 311)
216.5 02	Tap Factory From 4	406 Vesta
216.5	Dye Test Visible @ TF -	toilet
216.5	Dye Test Visible @ TF -	downspout
216.5	End of Survey DYE TE	EST COMPLETED